

Co., Ltd.

156-062737-001 Site amfori ID:

Report No.: JSASCN25918289 **Audit Date:** May 15-16, 2025

Page 1 of 6



The gate of industrial park



Factory name







Materials and finished goods warehouse



Mould making



Crushing and mixing



Co., Ltd.

156-062737-001 Site amfori ID:

Report No.: JSASCN25918289 **Audit Date:** May 15-16, 2025

Page 2 of 6



Injection molding




Pad printing (it was not in production during audit)



Assembling and Packing



Fire facilities



Evacuation plan map



Emergency light testing



Co., Ltd.

156-062737-001 Site amfori ID:

Report No.: JSASCN25918289 **Audit Date:** May 15-16, 2025

Page 3 of 6





Fire alarm testing

Fire hydrant testing







The curing worker worn PPEs properly



Chemical stored in explosion-proof cabinet



Safety label for chemicals



Co., Ltd.

Site amfori ID: 156-062737-001 Report No.: JSASCN25918289 **Audit Date:** May 15-16, 2025

Page 4 of 6





MSDS Eye washer






Safeguard

Warning sign on electric box







Attendance recorder



Co., Ltd.

156-062737-001 Site amfori ID:

Report No.: JSASCN25918289 **Audit Date:** May 15-16, 2025

Page 5 of 6





First aid kit

Drinking water





Toilets

Suggestion box



NC (7.6): The up and down moulds worker did not wear provided safety shoes and safety helmets.



NC (7.6): The laser carving worker did not wear provided dust-proof mask and protective goggles.



Co., Ltd.

Site amfori ID: 156-062737-001 Report No.: JSASCN25918289 **Audit Date:**

May 15-16, 2025

Page 6 of 6

----- END -----