Total Quality. Assured.

TEST REPORT

NUMBER : TSNT01889143

Original Picture



Intertek Testing Services (Tianjin) Ltd.
1-6F, Block B, No.7, Guiyuan Rd., High-tech Zone, Tianjin, China 300384
天津市高新区桂苑路7号B座1-6层 邮编：300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Website: www.Intertek.com

intertek
Total Quality. Assured.

TEST REPORT

NUMBER : TSNT01889143

Applicant : Rizhao Dongsheng Carpet Co., Ltd
South Of Shanhai 2 Road, West Of Chaoshi Road, Rizhao, Shandong, China
Attn : Chen Jing

Date : Dec 18, 2025

Sample Description As Declared :

No. Of Sample	:	One
Fibre Content	:	100% Nylon
Material	:	Rug
Finishing	:	Without Flame Retardant
End Uses	:	Rug
Colour	:	Brown
Style No.	:	-
Order No./PO No.	:	-
Buyer's Name	:	-
Agent's Name	:	-
Manufacturer's Name	:	-

Applicant's Provided Care Instruction/Label : -

Date Received/Date Test Started : Dec 12, 2025

Tests Conducted:
As Requested By The Applicant, For Details Refer To Attached Page(S)

Conclusion:
Based Upon The Results Of The Flammability Test Reported, The Sample Submitted For Testing Meets The Performance Requirements Of ASTM D2859-16(2021).

Authorized By :
For Intertek Testing Services
(Tianjin) Ltd.



Patrick Gong
General Manager

Intertek Testing Services (Tianjin) Ltd.
1-6F, Block B, No.7, Guiyuan Rd., High-tech Zone, Tianjin, China 300384
天津市高新区桂苑路7号B座1-6层 邮编: 300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Website: www.Intertek.com

Tests Conducted:

1 Flammability Test For Carpets And Rugs (ASTM D2859-16(2021)):

Requirement

(1) A Single Test Specimen Has Passed The Test If The Charred Portion Of The Tested Specimen Does Not Extend To Within 25 ±0.5 mm (1.0 in.) Of The Edge Of The Hole In The Steel Frame At Any Point.

(2) The Textile Floor Covering Material Has Passed The Test If Seven Of The Eight Test Specimens Have Met The Requirements In (1).

Test Result :

The Nearest Distance From Burnt Area To The Frame Edge

Original (mm)	
78	82
82	80
80	78
77	79

Interpretation Of Test Result :

Number Of Specimens Meet The Test Criterion	8

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

Intertek Testing Services (Tianjin) Ltd.
1-6F, Block B, No.7, Guiyuan Rd., High-tech Zone, Tianjin, China 300384
天津市高新区桂苑路7号B座1-6层 邮编: 300384
Tel: +86 22 8371 2202 Fax: +86 22 8371 2205
Website: www.Intertek.com